

TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)

1. Name of Officer : Jisha M V
2. Name of School : Ansar School, Padinjarangadi
3. Location/with name of Education
District/Sub District : Padinjarangadi/Ottapalam/Thrithala
4. Classification of building and size : Permanent
1. 33.40m X7.40m X3.60mtr Ground Floor-
2. 33.40m X7.40m X3.60mtr First Floor-
3. 33.40m X7.40m X3.60mtr Second Floor-
5. Period of which the certificate issued : 2022-2023
6. Nature of defects if any
- a) Foundation and basement : Nil
- b) Superstructure : Nil
- c) Doors & windows : Nil
- d) Wood work wrought and put up : Nil
- e) Roof : Nil
- f) Flooring : Nil
- g) Miscellaneous (cracks etc) : Nil
7. Any major defects noticed which will
Render the building unsafe in any manner: Nil
8. Whether maintenance works have been
Done properly : Yes
9. Whether the structure is sound on for
Conducting classes : The Structure is sound for conducting classes
under normal weather condition.

- Note: 1. The stability of the structure should be examined also with reference to location, Attitude, intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished seperately with the certificate.

Certified that the school was inspected by me on 13/feb/2023 and found to be fit to conduct classes for the academic period 2022-2023 for the reasons noted above.

Place: Kumaranellur
Date: 13/February/2023



Signature: 

Designation: Assistant Engineer
LSGD Section
KAPPUR